

Fixture observations and maintenance done on 9-17-2008

1 T12-Good	36 T12-Good
2 T12-Good	37 T12-Good
3 T12-Good	38 T12-Good
4 Replaced T12s	39 Replaced T12s
5 T12-Good	40 Replaced T12s
6 Installed missing T12s	41 T12-Good
7 T12-Good	42 T12-Good
8 T12-Good	43 T12-Good
9 T12-Good	44 T12-Good
10 T12-Good	45 T12-Good
11 T12-Good	46 T12-Good
12 T12-Good	47 Replaced T12s
13 T12-Good	48 T12-Good
14 T12-Good	49 Installed missing T12s
15 T12-Good	50 T12-Good
16 T12-Good	51 T12-Good
17 T12-Good	52 T12-Good
18 Upg raded to T8 Ballast+Lamps	53 T12-Good
19 T12-Good	54 Replaced T12s
20 Replaced T12s	55 T12-Good
21 T12-Good	56 Replaced T12s
22 Replaced T12s	57 T12-Good
23 T12-Good	58 T12-Good
24 T12-Good	59 T12-Good
25 T12-Good	60 T12-Good
26 Upg raded to T8 Ballast+Lamps	61 T12-Good
27 T12-Good	62 T12-Good
28 Upg raded to T8 Ballast+Lamps	63 T12-Good
29 T12-Good	64 T12-Good
30 T12-Good	65 Replaced T12s
31 T12-Good	66 T12-Good
32 Installed missing T12s	67 T12-Good
33 T12-Good	68 T12-Good
34 T12-Good	69 T12-Good
35 T12-Good	70 T12-Good